## **BUILDING CODE**

ANDY WRIGHT CHIEF OF BUILDING CODE (302) 855-7860 T (302) 855-7869 F





## **EXCEPTIONS TO 2012 IRC**

|    | IRC 2012  | <b>EXCEPTIONS</b>   |
|----|---|---|
| 1. | R-309.2 Carports  | Carports will be excluded from inspections.   |
| 2. | R-311.3 Landings. There shall be a landing on each side of each exterior door.  | A landing is not required on the exterior of a sliding door.                          |
| 3. | R-311.7.5.1 Riser Height. Maximum riser height shall be 7 ¾"  | Maximum riser height 8 ¼"   |
| 4. | R-311.7.5.1 Riser Height Difference.<br>The greatest riser height within any<br>flight of stairs shall not exceed the<br>smallest by more than 3/8"                 | The <u>first &amp; last</u> step, of interior stairs, may have a difference of 5/8"   |
| 5. | R-311.7.5.2 Tread Depth. Minimum tread depth shall be 10".  | Minimum tread depth 9" including winders.   |
| 6. | R-403.1.6 Foundation Anchorage. There shall be a minimum of two bolts per plate section with one bolt located not more than 12" from each end of the plate section. | No anchor bolts will be required at the end of each plate section, excluding corners. |
| 7. | R-313 Automatic Fire Sprinkler System<br>An automatic residential fire sprinkler<br>system shall be installed in townhouses   | No automatic residential fire sprinkler system will be required in townhouses and     |



one- and two- family

dwellings, under four stories.

and one- and two- family dwellings.